

Service Bulletin FEEDING

The feeding mechanism in the MkIV” (bis) is greatly improved. Customers having older machines (nos. <700) that have problems with the infeed* should

- a) Change the entire feeding mechanism.
- or
- b) Change to the new ejector.

a. New feeding mechanism

If the Duplimate has been used extensively, it could happen that there is a slack in the feeding mechanism. The easiest way to check this is to hold the anchor with one hand, while you are trying to move the ejector launch with the other hand. If you can move the ejector launch more than approximately 2 mms (while the anchor is still), you are advised to change the entire mechanism. See** part no. 05-00-028.

If there is no slack, and no other problem, we suggest that you do nothing further. If there is no slack, but you have other problems, you could consider to change the entire mechanism, but usually it is sufficient to change the ejector (only).

b. New ejector launch

If it takes more than one stroke to feed one card, you should first examine the playing cards and then (if there is nothing wrong with the cards) change the ejector.

WHAT IT COSTS

See** art no. 05-00-028 and 05-00-18 respectively.

Note that the fixed price for changing the entire feeding mechanism is only valid when we do it here in Sweden.

support@duplimate.com in January 2005

*Problems with the infeed means that it takes more than one stroke to feed one card and/or that you get several misduplicates.

**You will find prices, descriptions and instructions at the Supermarket. Go to <http://www.bridge-shop.com> and Category “Spares for Dup”.